



NORTHWEST LRT - 137 AVENUE STATION



Shared use path & cycle facilities

Seamless LRT and bus exchange

Property Impact

Pedestrian crossings provided

Local service road and parking provided

Shared use path

New traffic signal to accommodate LRT and bus turning movements

Property Impact

Reprogrammed traffic signal to accommodate LRT and turning movements

Removal of slip lanes to improve pedestrian crossing

Traffic lanes reduced south of 137 Avenue



TRANSIT ORIENTED DEVELOPMENT (TOD)
 At station locations, City policy supports transit oriented development, as specified in the TOD Guidelines or determined through a station area planning process.

LEGEND

LRT at Grade	Bus Stop	LRT Equipment Room
Underground LRT	Signal Intersection	Trees / Planting
Elevated LRT	Directional Arrows	Bicycle Parking
LRT Station	Pavement Markings	
Roadworks	Fence	
Shared Use Path	Access Closed	
Sidewalk	Pedestrian Crossing	
On-Street Parking		
Property Required		